



Photo 15: Looking northeast from Sites Lodoga Road toward the Peninsula Hills Recreation Area location.



Photo 16: Looking west from Huffmaster Road toward the Antelope Island Recreation Area location.

FIGURE 30-2J
Peninsula Hills and Antelope Island
Recreation Areas
Landscape Character Photos
Sites Reservoir Project EIR/EIS



Photo 17: Looking east from Huffmaster Road toward the Lurline Headwaters Recreation Area location.



Photo 18: Looking south from Peterson Road toward the South Bridge alignment from within the inundation area.

FIGURE 30-2K
Lurline Headwaters Recreation Area
and South Bridge
Landscape Character Photos
Sites Reservoir Project EIR/EIS



Photo 19: Looking east toward the Sites Pumping/Generating Plant location, from outside the inundation area.



Photo 20: Looking east from Peterson Road (within the Sites Reservoir Inundation Area) toward Sites Reservoir Inlet/Outlet structure location.

FIGURE 30-2L
Sites Reservoir Pumping/Generating
Plant and Inlet/Outlet Structure
Landscape Character Photos
Sites Reservoir Project EIR/EIS

This page intentionally left blank.



Photo 21: Looking west at the existing Funks Reservoir toward the Field Office Maintenance Yard location (to the right of center of photo) from the downstream side of Funks Reservoir near Funks Creek and the Funks Dam Spillway.

FIGURE 30-2M
Field Office Maintenance Yard
and Existing Funks Reservoir
Landscape Character Photo
Sites Reservoir Project EIR/EIS



Photo 22: Looking east at the Holthouse Reservoir location from the downstream side of Funks Reservoir near Funks Creek and the Funks Dam Spillway.

FIGURE 30-2N
Holthouse Reservoir Complex
Landscape Character Photo
Sites Reservoir Project EIR/EIS



Photo 23: Looking east and southeast toward the proposed GCID Canal Headgate Structure and Canal Lining location from the west side of the GCID Canal.

FIGURE 30-20
Proposed GCID Canal Headgate
Structure and Canal Lining Location
Landscape Character Photo
Sites Reservoir Project EIR/EIS

This page intentionally left blank.



Photo 24: Looking east toward the proposed GCID Canal Railroad Siphon Replacement location from the east side of Tehama Street/Highway 99W atop the GCID Canal berm.



Photo 25: Looking west at the proposed GCID Canal Railroad Siphon Replacement location from the east side of the railroad tracks atop the GCID Canal berm.

FIGURE 30-2P
GCID Canal Railroad Siphon
Replacement
Landscape Character Photos
Sites Reservoir Project EIR/EIS



Photo 26: Looking west from the east side of the Sacramento River at the Red Bluff Pumping Plant.



Photo 27: Looking northwest along the alignment of the TRR to Funks Creek Pipeline near the Outlet location at the Funks Creek crossing of McDermott Road.

FIGURE 30-2Q
Red Bluff Pumping Plant
and TRR Facilities
Landscape Character Photos
Sites Reservoir Project EIR/EIS



Photo 28: Looking southwest from McDermott Road and the residences near the northeast corner of the TRR toward the TRR location.



Photo 29: Looking northwest from McDermott Road and Lenahan Road toward the TRR location.

FIGURE 30-2R
Terminal Regulating Reservoir
Landscape Character Photos
Sites Reservoir Project EIR/EIS

This page intentionally left blank.



Photo 30: Looking south from Sutton Road approximately 0.25 mile south of Delevan Road toward the Sites/Delevan Overhead Power Line Line and Delevan Pipeline location.

FIGURE 30-2S
Sites/Delevan Overhead Power Line
and Delevan Pipeline
Landscape Character Photo
Sites Reservoir Project EIR/EIS



Photo 31: Looking south from Corbin Road approximately 0.25 mile south of Delevan Road toward the Delevan Overhead Power Line and Delevan Pipeline location.

FIGURE 30-2T
Delevan Overhead Power Line
and Delevan Pipeline
Landscape Character Photo
Sites Reservoir Project EIR/EIS



Photo 32: Looking south (downstream) from the Maxwell Irrigation District facility on the west side of the Sacramento River toward the Delevan Pipeline Intake and Discharge Facilities location.



Photo 33: Looking northeast from Huffmaster Road toward the Communication Towers from within the inundation area.

FIGURE 30-2U
Delevan Pipeline Intake/Discharge
Facilities and Communication Towers
Landscape Character Photos
Sites Reservoir Project EIR/EIS

This page intentionally left blank.



Photo 34: Looking south along the Overhead Power Line (Alternate Alignment), on State Route 45 near Willow Creek Road.

FIGURE 30-2V
Overhead Power Line
(Alternate Alignment)
Landscape Character Photo
Sites Reservoir Project EIR/EIS



Photo 35: Looking south towards the proposed Boat Ramp Recreation Area, along Sites Lodoga Road.

FIGURE 30-2W
Boat Ramp
Landscape Character Photo
Sites Reservoir Project EIR/EIS