

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

FARRAR PARK AT DUTCH SLOUGH
WATER QUALITY REPORT

OCTOBER 2018

RUN DATE: November 13, 2018

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|-------|-------|-------|
| 1 | 1,267 | 1,124 | 1,217 |
| 2 | 1,254 | 1,114 | 1,208 |
| 3 | 1,277 | 1,101 | 1,207 |
| 4 | 1,292 | 1,100 | 1,209 |
| 5 | 1,283 | 1,095 | 1,200 |
| 6 | 1,281 | 1,118 | 1,207 |
| 7 | 1,280 | 1,080 | 1,191 |
| 8 | 1,258 | 1,084 | 1,178 |
| 9 | 1,294 | 1,102 | 1,190 |
| 10 | 1,387 | 1,120 | 1,225 |
| 11 | 1,414 | 1,114 | 1,242 |
| 12 | 1,402 | 1,091 | 1,230 |
| 13 | 1,378 | 1,076 | 1,231 |
| 14 | 1,410 | 1,105 | 1,251 |
| 15 | 1,333 | 1,048 | 1,196 |
| 16 | 1,285 | 1,061 | 1,194 |
| 17 | 1,284 | 1,078 | 1,192 |
| 18 | 1,294 | 1,075 | 1,190 |
| 19 | 1,280 | 1,070 | 1,181 |
| 20 | 1,283 | 1,078 | 1,183 |
| 21 | 1,340 | 1,095 | 1,212 |
| 22 | 1,402 | 1,119 | 1,249 |
| 23 | 1,434 | 1,139 | 1,270 |
| 24 | 1,425 | 1,120 | 1,252 |
| 25 | 1,410 | 1,097 | 1,241 |
| 26 | 1,381 | 1,084 | 1,231 |
| 27 | 1,370 | 1,072 | 1,229 |
| 28 | 1,443 | 1,064 | 1,259 |
| 29 | 1,427 | 1,075 | 1,249 |
| 30 | 1,324 | 1,026 | 1,201 |
| 31 | 1,269 | 1,016 | 1,164 |

Comments:

0 reading indicates that the station was out of service.